



Technical support

SONOSITE remains committed to the safety and security of its customers. For further questions, please contact SONOSITE technical support:

Phone (U.S. or Canada) [\(877\) 657-8118](tel:877-657-8118)

Phone (Outside U.S. or Canada) [\(425\) 951-1330](tel:425-951-1330), or call your local

representative

Fax: (425) 951-6700

Cybersecurity Alert – PHP2Shell

FUJIFILM SONOSITE, Inc. is aware of the cybersecurity advisories published by the following agencies:

- **NSA** (<https://www.nsa.gov/press-room/press-releases-statements/press-release-view/article/4630238/nsa-advisory-critical-patches-recommended-for-php-vulnerabilities/>)
- **CISA** Advisory Oct. 21st, 2026 (<https://www.cisa.gov/news-events/alerts/2026/10/21/critical-vulnerabilities-php-require-immediate-patching>)

Reported vulnerabilities

CVE-2026-109618 (Memory Corruption)

CVE-2026-109619 (Stale Global State)

CVE-2026-115560

Sonosite impact assessment

We have evaluated the potential impact on our ultrasound systems and services and determined that they are **not affected** by these vulnerabilities, as PHP is not deployed on SONOSITE systems.

The following systems are **not affected by any of the CVEs listed above**:

- SONOSITE MT ultrasound system
- SONOSITE iLOOK ultrasound system
- SONOSITE PX ultrasound system
- SONOSITE LX ultrasound system
- SONOSITE ST ultrasound system
- SONOSITE ZX ultrasound system
- SONOSITE Edge II ultrasound system
- SONOSITE SII ultrasound system
- SONOSITE iViz ultrasound system
- SONOSITE X-Porte ultrasound system
- SONOSITE Edge ultrasound system
- SONOSITE NanoMaxx ultrasound system
- SONOSITE M-Turbo ultrasound system
- SONOSITE S Series ultrasound systems
- SONOSITE MicroMaxx ultrasound system
- SONOSITE Titan ultrasound system
- SONOSITE 180 ultrasound system
- SONOSITE SonoHeart ultrasound system
- FUJIFILM FC1 ultrasound system
- SONOSITE Synchronicity