Technical support

SONOSITE remains committed to the safety and security of its customers. For further questions, please contact SONOSITE technical support:

Phone (U.S. or Canada) (877) 657-8118
Phone (Outside U.S. or Canada) (425) 951-1330, or call your local representative
Fax: (425) 951-6700

Cybersecurity Alert – UEFI firmware vulnerability

FUJIFILM SONOSITE, Inc. is aware of the cybersecurity advisories published by the following agencies:

- **NIST** (https://nvd.nist.gov/vuln/detail/cve-2026-97631)

Reported vulnerabilities

CVE-2026-97631

SONOSITE impact assessment

We have evaluated the potential impact on our ultrasound systems and services and determined that they are **not affected** by these vulnerabilities, as network boot rom is disabled on our products and the vulnerability can only be exploited if PXE boot is actually invoked and the EFI network drivers are loaded.

The following systems are **not affected by any of the CVEs listed above**:

- SONOSITE MT ultrasound system
- SONOSITE iLOOK ultrasound system
- SONOSITE PX ultrasound system
- SONOSITE LX ultrasound system
- SONOSITE ST ultrasound system
- SONOSITE ZX ultrasound system
- SONOSITE Edge II ultrasound system
- SONOSITE SII ultrasound system
- SONOSITE iViz ultrasound system
- SONOSITE X-Porte ultrasound system
- SONOSITE Edge ultrasound system
- SONOSITE NanoMaxx ultrasound system
- SONOSITE M-Turbo ultrasound system
- SONOSITE S Series ultrasound systems
- SONOSITE MicroMaxx ultrasound system
- SONOSITE Titan ultrasound system
- SONOSITE 180 ultrasound system
- SONOSITE SonoHeart ultrasound system
- FUJIFILM FC1 ultrasound system
- SONOSITE Synchronicity