

**FUJIFILM Sonosite, Inc.**  
21919 30th Dr. SE  
Bothell, WA  
98021-3904  
USA

**Tel:** 1.425.951.1200  
**Fax:** 1.425.951.1201  
[www.sonosite.com](http://www.sonosite.com)

October 1, 2024

**End of Support Notice –Sonosite Edge II and Sonosite SII Ultrasound Systems and Transducers – Veterinary Configurations**

To our valued customers in Canada,

It is our goal, and responsibility, to ensure that you receive timely updates about Fujifilm Sonosite products. In February 2022 we informed you of the retirement of Sonosite Edge II and Sonosite SII ultrasound system veterinary configurations and transducers. We are now confirming the end of support dates for these products.

Items included in this end of sale notice are:

Sonosite Edge II ultrasound system veterinary configuration  
Sonosite SII ultrasound system veterinary configuration

L52x Transducer - Vet  
rC60xi Transducer - Vet  
HFL50x Transducer - Vet  
HSL25x Transducer - Vet  
C11x Transducer - Vet  
HFL38xi Transducer - Vet  
C35x Transducer - Vet

L25x Transducer - Vet  
P21x Transducer - Vet  
rP19x Transducer - Vet  
P10x Transducer - Vet  
L38xi Transducer - Vet  
ICTx Transducer - Vet

Service Support of the above listed products will be provided until the dates listed below

Sonosite Edge II Veterinary Systems - New	June 30, 2030
Sonosite SII Veterinary Systems - New	September 30, 2030
Sonosite Veterinary Transducers - New	September 30, 2030
Sonosite Veterinary Transducers - Remanufactured	September 30, 2030

If you have any questions about service support please contact your Fujifilm Sonosite Technical Support Team or your authorized Fujifilm Sonosite representative.

We sincerely thank you for your continued support.

Marnie Hamp  
Senior Manager, Product Management  
FUJIFILM Sonosite, Inc.